

Fuji Xerox Direct Management Console Supported Models

Fuji Xerox Direct Management Console Supported Models

Product Name	Device Management	Operation of Applications to Device (Install / Update / Uninstall)
ApeosPort 2560 ApeosPort 3060 ApeosPort 3560	■	■
ApeosPort 4570 ApeosPort 5570	■	■
ApeosPort C2060 ApeosPort C2560	■	■
ApeosPort C3070 ApeosPort C3570 ApeosPort C4570 ApeosPort C5570 ApeosPort C6570 ApeosPort C7070	■	■
ApeosPort-V 2060 ApeosPort-V 3060 ApeosPort-V 3065	■	■ *1
ApeosPort-V 4020	■	■ *2
ApeosPort-V 4070 ApeosPort-V 5070	■	■ *3
ApeosPort-V 6080 ApeosPort-V 7080	■	■ *4
ApeosPort-V C2275 ApeosPort-V C3373 ApeosPort-V C3375 ApeosPort-V C4475 ApeosPort-V C5575 ApeosPort-V C6675 ApeosPort-V C7775	■	■ *5
ApeosPort-V C2276 ApeosPort-V C3374 ApeosPort-V C3376 ApeosPort-V C4476 ApeosPort-V C5576 ApeosPort-V C6676 ApeosPort-V C7776	■	■ *6
ApeosPort-V C3320	■	■ *2

Product Name	Device Management	Operation of Applications to Device (Install / Update / Uninstall)
ApeosPort-V C5580 ApeosPort-V C6680 ApeosPort-V C7780	■	■ *7
ApeosPort-V C5585 ApeosPort-V C6685 ApeosPort-V C7785	■	■ *8
ApeosPort-VI C2271 ApeosPort-VI C3370 ApeosPort-VI C3371 ApeosPort-VI C4471 ApeosPort-VI C5571 ApeosPort-VI C6671 ApeosPort-VI C7771	■	■
ApeosPort-VII 4021 ApeosPort-VII 5021	■	■
ApeosPort-VII C3321 ApeosPort-VII C4421	■	■
ApeosPort-VII C2273 ApeosPort-VII C3372 ApeosPort-VII C3373 ApeosPort-VII C4473 ApeosPort-VII C5573 ApeosPort-VII C6673 ApeosPort-VII C7773	■	■
ApeosPort-VII C5588 ApeosPort-VII C6688 ApeosPort-VII C7788	■	■
DocuCentre-V 2060 *9 *10 DocuCentre-V 3060 *9 *10 DocuCentre-V 3065 *9 *10	■	■ *1
DocuCentre-V 4070 *10 DocuCentre-V 5070 *10	■	■ *3
DocuCentre-V 6080 *10 DocuCentre-V 7080 *10	■	■ *4
DocuCentre-V C2263 DocuCentre-V C2265	■	■ *11

Product Name	Device Management	Operation of Applications to Device (Install / Update / Uninstall)
DocuCentre-V C2275 DocuCentre-V C3373 DocuCentre-V C3375 DocuCentre-V C4475 DocuCentre-V C5575 DocuCentre-V C6675 DocuCentre-V C7775	■	■ *5
DocuCentre-V C2276 DocuCentre-V C3374 DocuCentre-V C3376 DocuCentre-V C4476 DocuCentre-V C5576 DocuCentre-V C6676 DocuCentre-V C7776	■	■ *6
DocuCentre-V C5580 DocuCentre-V C6680 DocuCentre-V C7780	■	■ *7
DocuCentre-V C5585 DocuCentre-V C6685 DocuCentre-V C7785	■	■ *8
DocuCentre-VI C2271 DocuCentre-VI C3370 DocuCentre-VI C3371 DocuCentre-VI C4471 DocuCentre-VI C5571 DocuCentre-VI C6671 DocuCentre-VI C7771	■	■
DocuCentre-VII C2273 DocuCentre-VII C3372 DocuCentre-VII C3373 DocuCentre-VII C4473 DocuCentre-VII C5573 DocuCentre-VII C6673 DocuCentre-VII C7773	■	■
DocuCentre-VII C5588 DocuCentre-VII C6688 DocuCentre-VII C7788	■	■
DocuColor 7171 P	■	■ *12
DocuPrint CM415 AP	■	■ *2
DocuPrint M465 AP	■	■ *2

Product Name	Device Management	Operation of Applications to Device (Install / Update / Uninstall)
PrimeLink C9065 Printer PrimeLink C9070 Printer	■	■
Versant 180 Press Versant 80 Press Versant 80 Press (Model-2)	■	■ ^{*13}

Note: Products for sale may differ according to country or region. For more information, please contact the Fuji Xerox office or authorized dealers in each country/region.

Note: An application cannot be installed/updated/deleted on/from a device if the application does not support the device.

Note: Up to 100 MFDs can be registered with Fuji Xerox Direct Management Console.

- *1: The controller software version needs to be updated to version 1.0.31 or higher.
- *2: The controller software needs to be updated to version 1.2.7 or higher.
- *3: The controller software needs to be updated to version 1.0.15 or higher.
- *4: The controller software needs to be updated to version 1.0.14 or higher.
- *5: The controller software should be version 1.3.28 or higher for Type 1 (T1) model and version 2.1.17 or higher for Type 2 (T2) model.
- *6: The controller software needs to be updated to version 1.1.15 or higher.
- *7: The controller software should be version 1.3.27 or higher for Type 1 (T1) model and version 2.1.16 or higher for Type 2 (T2) model.
- *8: The controller software needs to be updated to version 1.2.14 or higher.
- *9: Needs to be equipped with HDD Extension Kit.
- *10: Needs to be equipped with Printer Kit.
- *11: The controller software needs to be updated to version 1.0.30 or higher.
- *12: The controller software needs to be updated to version 1.0.3 or higher.
- *13: The controller software needs to be updated to version 1.3.15 or higher.